RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	Attilakkamma temple, Surrounding area, mallasandra colony, Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	360-390 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	Shettyhalli main road, Surrounding area, mallasandra colony Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	350-380 rmt
06. Approximate Casing Pipe	45-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	Govt school opp, mallasandra colony, Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	360-390 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1000-1500 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	Opp Ucchangi temple, PK's Slum Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	360-380 rmt
06. Approximate Casing Pipe	45-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1500-2000 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	Shree shakthi bhavana, Surrounding area BHEL Mini colony Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	350-380 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1000-1500 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	Mallikarjuna swamy temple, Surrounding area BHEL Mini colony Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	350-380 rmt
06. Approximate Casing Pipe	30-40 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1000-1500 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 08.11.2019

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	PK's mustering centre surrounding area PK's Slum Ward no 13,
03. Purpose of Ground Water	Drinking water
04. Area	Mallasandra
05. Approximate Drilling Depth	350-380 rmt
06. Approximate Casing Pipe	40-50 rmt
07. PVC Pipe	10-15 rmt
08. Expected Yield	1000-1500 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner